
POWERTEC

WORKBENCH

WB-HR10



" Please note: The numbers you may find on parts may not correlate to the numbers are only to help ensure accurate packing. Warranty parts may d from originals, but the function will remain the same."	e assembly manual, these iffer slightly in appearance

HARDWARE LIST



19 1/2"x8t(qty:2)



20 1/2"x16t(qty:22)



21 Ø14ר28×2t(qty:44)





22 1/2"x3-1/2"(qty:14)



23 1/2"x3-1/4"(qty:2)



24 1/2"x3-3/4"(qty:6)



WB-HR10


PART LIST

Part	Description	QTY
1	Rear base tube	2
2	Tilted upright	2
3	Cross tube	2
4	Upper cross tube	1
5	Lower slide tube	2
6	Upper slide tube	2
7	Lower linkage tube	1
8	Base linkage tube	1
9	Linkage plate	2
10	Linkage plate	2
11	Handle bar	2
12	PVC tube	2
13	Round inner plug	2
14	PVC sleeve	2
15	Square inner plug	6
16	Bumper	2
17	Bumper	2
18	Plastic plate	2
19	Nylon nut	2
20	Nylon nut	22
21	Washer	44
22	1/2'*3-1/2' Half thread hex bolt	14
23	1/2'*3-1/4' Half thread hex bolt	2
24	1/2'*3-3/4' Half thread hex bolt	6
25	Screw	10
26	Rivet	2
27	Name plate	1





EXPLODED DIAGRAM




Remarks: All unmarked Washers are (21) and all unmarked Nylon Nuts are (20).

WB-HR10


ASSEMBLY ONE

Note before beginning assembly:


Always insert all bolts through holes prior to tightening
due to precision fit





WB-HR10



WB-HR10
Workbench Half Rack







POWERTEC®

WORKBENCH

POWERTEC INC.

601 W. Harford St. Milford PA 18337 Phone: (570) 296-5005 Fax:(570) 296-5009

www.powertecfitness.com

LIMITED LIFETIME WARRANTY